



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

Division of Oil, Gas and Mining  
JOHN R. BAZA  
Division Director

### Minerals Inspection Report

Reviewed 


Report Date:

Mine Name: Bald Knoll Mine	Permit Number: S/025/0012	Mine Status: Reclaimed
Operator Name: MMG Mining / Mark Carter	Inspection Date: November 13, 2013	Permit Fees: No Fee Req.
Inspector(s): Lynn Kunzler	Inspection Time: 11:30 am	Bond Amount: \$24,600
Attendee(s): none	Weather: clear and cool	Bond Escalation: 01/01/2013
Inspection Purpose: Evaluate recent reclamation activities		Prior Inspection:

#### Conclusions and Recommendations

This site is now considered reclaimed. All earth work and seeding was completed in early October of 2013. The Operator may request a partial bond release by submitting form MR-SITE.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i> The operator's lease on this area had expired. He was under a Division Directive to complete reclamation of the site by October 24, 2013. With the site now regraded and seeded, the operator may request a partial bond release. The Division should retain \$5,000 to assure revegetation success.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i> The area is behind locked gates to keep the public off this private land. All highwall areas have been reduced to a 2h:1v slope or flatter. There are no shafts or adits on this site. Trash has been removed.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i> The regraded surface was left in a roughened condition to help control erosion and promote vegetation growth. There are no drainages associated with this operation.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i> There is no deleterious materials left at this site. All fuels, oil, lubricants, etc. have been removed from the site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i> The access road to this site was pre-existing and does not require reclamation. This road was considered to be well maintained.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i> The Operator has completed all regrading and other earthwork required to reclaim this site. The area was seeding in October of 2013.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i>	<input type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i>	<input type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i>	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Mark Carter, Operator  
John Blake, SITLA

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M025-Kane/S0250012-BaldKnoll/inspections/insp-11132013.pdf